0032

CO-OP MINING COMPANY

P.O. Box 1245 Huntington, Utah 84528



(801) 381-5238 Coal Sales (801) 381-5777

May 6, 1993

Pamela Grubaugh-Littig Permit Supervisor Utah Division of Oil, Gas & Mining 3 Triad Center, Suite 350 Salt Lake City, Utah 84180-1203 RECEIVED MAY 0 6 1993

DIVISION OF

Ms. Grubaugh-Littig,

Re: Tank Seam Permitting, Co-Op Mining Company, Bear Canyon Mine, ACP/015/025-93B, Emery County, Utah

Enclosed are two copies of a proposal to add the Tank Seam to the current permit area. These modifications include the necessary changes for leaving the portal access road as a post-mining access road as requested by the property owner, C.O.P. Coal Development Company. Attached is a list outlining the changes pertaining to the proposal. Changes have been indicated in the text using a redline/strikeout format.

It is urgent that Co-Op begins operations in the Tank Seam immediately, and we request that the Division respond to the proposal as soon as possible. Any deficiencies noted by the Division will be addressed and resubmitted as soon as we receive the deficiencies.

Co-Op would also like to begin publishing for the Tank Seam permitting action immediately. Enclosed is a public notice for your review.

If you have any questions, please call Charles Reynolds at (801)381-2450.

Sincerely,

Wendell Owen Resident Agent

611 Muen

WJO/cr Enclosure(s)

## NOTICE

Co-Op Mining Company, P.O. Box 1245, Huntington, Utah hereby announces it's intent to file application to extend mining into the Tank Seam, located above the existing seam within the existing permit area of the Bear Canyon Mine (ACT/015/025) with the Division of Oil, Gas, and Mining under the laws of the State of Utah. This includes an additional surface disturbance of approx. 3.5 acres. The proposal also includes modifications to the plan to allow retention of the existing access road for postmining recreational uses as requested by the property owner, C.O.P. Coal Development Company. A copy of the complete application is available for public inspection at the Division of Oil, Gas, and Mining offices, 355 West, North Temple, Suite 350, Salt Lake City, Utah 84180-1203. Written comments on the appplication should be submitted to the State of Utah, Division of Oil Gas & Mining, at the above address. The area to be mined can be found on the USGS Hiawatha quadrangle map. The proposed mining and surface disturbance is within privately owned Fee The coal area is described as follows; T16S, R7E SLBM Fee Land; Sec. 14 SW1/4, SE1/4, Sec. 23 E1/2, E1/2 W1/2, Sec. 24 All West of N-S Fault, Sec. 25 All West of N-S Fault, Sec. 26 NE1/4 NE1/4, NW1/4 NE1/4, N1/2 SW1/4 NE1/4 and access/haul raod and topsoil storage area shown on Plate 2-1 of the Mining and Reclamation Plan

D.O.G.M. May 5, 1993 page #1

Page #	<u>Comments</u>
1-11 1-12 3-vi 3-4	"Post Mining Land-Use Variance" section added New page number. No change to text. Reference to Appendix 3-H added. Section 3.3.4 - new paragraph added "drop tube" from Tank Seam to Blind Canyon Seam. Note that only minimal surface structures will
3-6	be added. Section 3.3.10 - reference to new road added.
3-10	"Post-mining access road discussed. Table 3.3-1 - areas updated. Lower and Upper Portal Access roads combined. New Tank Seam
3-27	road and pad added. Table 3.4-1 - coal reserves added from Tank Seam.
3-28 3-36	Life of mine adjusted for Tank Seam coal. Sec. 3.4.6.2 - Operating schedule adjusted. Sec. 3.4.6.3 - Employee numbers adjusted.
3-37	Sec 3.5.1 - Reference to post-mining access road added. "total reclamation" reference
3-40	removed. Sec. 3.5.3 - Statement added for post-mining access road.
3-48 3-59 3-60 3-62 3-64 3-69 3-71 3-72 3-77 3-80 3-83 3-86	Disturbed changed to recontoured.  Post-mining access road referenced.  Existing text deleted  Post-mining access road referenced.  Post-mining access road referenced.  word "recontoured" added.  Tank Seam Portal Pad added.  Access road highwalls to remain.  word "reclaimed" added.  Sec. 3.6.6 - Reclamation dates adjusted.  Roads not reclaimed.  Portals added for Tank Seam. Backfilling and seeding reduced for access roads.  Portals added for Tank Seam.
3-89	Backfilling and seeding reduced for access roads.
3C-4 3D-4 3D-5 App. 3-H App. 3-L	Tank Seam Subsidence calculations added. Post-minng access and Tank Seam referenced. Post-mining access road to remain. Tank Seam Access Road Construction with cut and fill calculations. Updated for post-mining access road.
4-7 4-11	Recreation better defined. Post-mining access road referenced. Portal Access roads added.

D.O.G.M. May 5, 1993 page #2

## 4A-3Letter from property owner added. App. 4-B Post-Mining Land-Use Variance. Description added Plates 6-9 thru 6-12 added 6-iii 6-16 Tank Seam referenced 6 - 17Tank Seam referenced 6A-21 thru 6A-31 Tank Seam Drill Hole Logs added 7-iv Sec. 7.2-17 added. 7-vi Plate 7-1E added 7-87,87A Table 7.2-10 - Diversions revised and added for Tank Seam 7-89,89A Table 7.2-11 - Culverts revised and added for Tank Seam 7-104,104A Tank Seam Hydrology discussed. 7-106A Figure 7.2-17 added for Tank Seam Portal Pad Catch Basin 7-124 Post-mining access road referenced. App 7-G Diversion designs added and revised for Tank Seam. Арр. 7-Н Post-mining diversions revised for post-mining access road. App 7-J PHC updated fro Tank Seam potential impacts. App 7-K BTCA areas H & I added for Tank Seam 8-26 Table 8.9-1 - Adjustments made for Tank Seam and postmining access road. 8-27 Post-mining access road referenced 8-36 & 37 Tank Seam Access Road and Portal Pad. New Section 8.9.5 8-38 Sec. 8.9.5 now numbered 8.9.6. 8-39 New page number. 8-40 Sections on soil redistribution adjusted for Tank Seam thru Access Road, Tank Seam Portal Pad and Post-mining access 8-43 road. 8-44 Sec 8.11 new page number. Table 8.11-1 - Adjustments made for Tank Seam and post-mining access road. 8A-16&17 Tank Seam soil sample test results added 9-ii New Sec 9.3.5 added, old renumbered 9.3.6 9-iii App 9-E added 9-10 Section 9.3.5 - Tank Seam vegetation discussed Old Sec 9.3.5 is now Sec 9.3.6 9-10A App 9-E Tank Seam Access Road Vegetation Sampling.

Comments

Page #

D.O.G.M. May 5, 1993 page #3

## Plates Comments 2-4C Revised for Tank Seam 2-4E New Surface Facilities Map Tank Seam 3-1 Tank Seam Portal Pad cross section added 3-2A,B,C,DRevised for Post-mining access road and Tank Seam. 3-2E Added for Tank Seam 3-4C Underground Mining Projections for Tank Seam 3-5C Revised to show Tank Seam Access Road 6-9 thru 6-12 New geology plate for Tank Seam 7-1C Revised for Tank Seam 7-1E New Hydrology map for Tank Seam 7 - 4Disturbed area revised for Tank Seam 7-5 Revised watersheds for Tank Seam area 7-7 Revised Post-Mining watersheds for the post mining access road and Tank Seam. 7-8A&B Post-mining drainage profiles revised. 8-1 Revised for Tank Seam 8-5C&D Revised for post-mining access road and Tank Seam. 8-5E New plate for Tank Seam